

**Hyannis Maintenance Dept.**

**From:** "Hyannis Maintenance Dept." <colair@██████████>  
**To:** <mike\_jolicœur@██████████>  
**Cc:** <tim\_green@██████████>  
**Sent:** Monday, August 25, 2003 2:23 AM  
**Subject:** Trim Actuators Acft UE-40

Good morning Mike :

This is Perry from Colgan air per your request I am submitting a request for a configuration change to UE-40. We are changing the elevator trim actuators both left & right due to play in the barrels per Beach MM 27-30-01. The IPC calls for P/N 129-526033-3 to be installed in both the left and right elevators how ever do to logistics the parts are non-available. The IPC shows to replace both actuators with 129-526033-27 & 28 both up numbers are not yet available in the system. I have a 129-526033-7 left trim actuator and a 129-526033-8 right trim actuator how every the IPC usable on code will not allow me to install them due to aircraft S/N number requirements. The following information is submitted.

Perry Sarluca  
Colgan-air  
██████████ Fax  
P/O 11487  
Beech 1900D S/N N240CJ UE-40  
Acft TT 16503.8  
Acft TL 24637

Remove P/N 129-526033-3 S/N Unk from left elev trim and install P/N 129-526033-7 S/N PAA010903. Remove P/N 129-526033-3 S/N Unk from right elev trim and install P/N 129-526033-8 S/N 678-F-98. This Acft is AOG

Yours Truly  
Perry Sarluca  
Hyannis Maintenance Supervisor  
██████████ Fax