

**DRIVESHAFT REMOVALS AND REINSTALLATIONS FOR OTHER MAINTENANCE
N917AL**

DATE	AIRCRAFT TOTAL TIME	REMOVED AND REPLACED FOR
05-04-01	2114.2	Forward end of IDS failed and decoupled from transmission. Flight terminated with an auto-rotation to the water. Shaft S/N KC734.
04-10-01	1998.0	R&R IDS for Transmission change
4-01-01	1975.4	R&R IDS for Pylon beam replacement
3-30-01	1839.7	R&R IDS for R/H Corner mount change, front & rear.
12-31-00	1644.4	R&R IDS for Engine Compressor change
10-01-00	1297.7	R&R IDS for Engine Compressor change
7-22-00	995.6	R&R IDS for Pylon beam change
7-3-00	906.7	R&R IDS for Freewheeling unit change
7-1-00	893.9	R&R IDS for forward and aft engine PTO seals
6-19-00	833.1	R&R IDS for Transmission change
9 removals prior to failure		