

Supplemental Report Photographs

Rochester, Indiana

HWY19MH003

(3 pages)



Photo #1 A close-up of the on-scene post-crash view of school bus with lights in operation. (Source: Indiana State Police)



Photo #2 On-scene post-crash view of school bus with lights in operation (Source: Indiana State Police)



Photo #3 Extended stop arm with two stop signs on school bus (Source: Bus Safety Solutions Inc.)



Photo #4 Close-up view of extended stop arm with single stop sign and horizontal stop bar (Source: S.A.F.E. Gates)