

DOCKET NO. SA-515

**NATIONAL TRANSPORTATION SAFETY BOARD
WASHINGTON, D.C.**

ATTACHMENT C

**PHOTOGRAPHIC SUPPLEMENT
(5 PAGES)**

BY: HENRY F. HUGHES




Photo 1.
View of front of airplane note airstairs.




Photo. 2.
Left side overwing emergency
window exits, all 4 overwing
exits were used.




Photo. 3.
View of tailcone area and airstairs.



Photo. 4.
Damaged area on left
side of airplane.



Photo. 5.
Closeup exterior view
of damage to left side
at row 37.



Photo. 6.
Interior view of row 37 left side
seats 37 A,B, and C.




Photo. 7.
Overall view of left side of aft cabin.



Photo. 8.
View of row 38 seats A, B, and C.
Note PSU and other debris




Photo. 9.
Right side of cabin at row 37.
Note 5 exit holes.