



Survival Factors 6 - Photo 13. Fuselage damage, left side, with commingled approach light structure.