



Survival Factors 6 - Photo 33. Interior damage, seat unit 4 EF, showing floor disruption.