



**Survival Factors Attachment:**

**Photographs**

**Oakland, Ia.**

**HWY18MH003**

(9 pages)



Photo #1: Exterior of school bus showing extensive fire damage at the scene



Photo #2: Left side exterior view of school bus showing extensive fire exposure.



Photo #3: Front interior view of bus showing extensive fire damage at location of manual door release handle



Photo #4: Interior close-up of driver's area showing extensive fire damage



Photo #5: Interior of passenger compartment of school bus showing structural buckling



Photo #6: Interior close-up of rear roof hatch, missing cover and deformation to roof.



Photo #7: Interior view of the rear emergency door and fire damage to passenger compartment



Photo #8: Interior close-up of rear emergency door and interior handle



Photo #9: Photo of fire damaged fire extinguisher in overhead compartment



Photo #10: Close-up of fire damaged fire extinguisher in overhead compartment



Photo #11: Close-up of fire damaged extinguisher



Photo #12: Exterior side view of exemplar school bus showing location of emergency windows



Photo # 13: Interior view of driver's area in exemplar school bus showing manual door release handle



Photo #14: Close-up of manual door release handle in exemplar school bus





Photo #15: Interior view of passenger compartment in exemplar school bus



Photo #16: Close-up of rear emergency door and handle in exemplar school bus