



Survival Factors Attachment: Scene photographs

Biloxi, Mississippi

HWY17MH010010

(8 pages)




Photo #1: The lead locomotive showing the impact area and collision damage



Photo #2: The exterior left side of motorcoach showing impact damage



Photo #3: Exterior right side of motorcoach showing the cut away rear door



Photo #4: Interior of motorcoach at point of impact with the train



Photo #5: Exterior close-up view of cut away rear door of motorcoach



Photo #6: Interior view of rear door emergency release valve and handle location



Photo #7: Exterior view of rear door on exemplar motorcoach



Photo #8: Interior close-up view of emergency door handle placement



Photo #9: Defective seatbelt buckle on motorcoach



Photo #10: Taped defective seatbelt buckle on motorcoach



Photo #11: Defective aisle seatbelt buckle on motorcoach



Photo #12: Defective aisle seatbelt buckle on motorcoach



Photo #13: Defective seatbelt buckle for window seat



Photo #14: Defective seatbelt buckle for window seat