



Details of the lower right rear portion of the SUV are visible. The right rear wheel with burned away tires and damaged right rear quarter panel are visible. A section of third rail is protruding from the upper left corner of the wheel well, and is in contact with the wheel.