



A detailed portion of the lower aft portion of the driver seat is visible. The driver seat belt buckle is visible, with severe fire damage having melted away most of the non-metal parts.