



The front and a portion of the right side of the SUV is visible. The severe inward crushing of the right side is visible.