



The rear and a portion of the right side of the SUV is visible. The railroad rail protruding from the right rear corner of the car is visible and the severe crushing of the right side of the car is visible.