



W234
Broken
WIRE (S)

Systems 9 - 747-SL-20-048 - Fig. 17. Connector backshell without proper buildup tape to the bundle.