



Systems 9 - 747-SL-20-048 - Fig. 1. Vibration caused chafing under the bundle clamp. Note that the clamp cushion shows little sign of wear.