



Systems 9 - 747-SL-20-048 - Fig. 10. Sleeving over splices failed, allowing splice corrosion.