



Systems 9 - 747-SL-20-048 - Fig. 12. Moisture resistant closed end splices correctly oriented up (Reference document, section 20-30-12). If they become oriented downward they can trap moisture, causing corrosion.