



Systems 9 - 747-SL-20-048 - Fig. 13. Clumps created by concentrating a large number of splices on the flight deck floor crossover bundle. Splices should be staggered throughout the bundle, this reduces the potential for wire - to - wire (text cut-off).