



Systems 9 - 747-SL-20-048 - Fig. 15. Damage from hydraulic fluid on a connector grommet. Initially a color change is observed, then cracking occurs as the grommet dries out. If contamination is severe enough, all grommet material may be eroded.