



Systems 9 - 747-SL-20-048 - Fig. 16. Chemical contamination resulting in a loss of elasticity to the connector grommet. This can result in internal connector contamination as the environmental seal is