



BACKSHELL
BUILD-UP
MISSING

Systems 9 - 747-SL-20-048 - Fig. 18. Wires broken at the connector backshell.