



Systems 9 - 747-SL-20-048 - Fig. 19. Missing connector filler rods. The compromised environmental seal can contribute to internal connector corrosion.