



VARGLAS SLEEVING
UNDER CLAMP
DAMAGED

Systems 9 - 747-SL-20-048 - Fig. 2. Vibration caused chafing under bundle clamp. Here, only the sleeving is damaged, but if not corrected, damage will likely occur to the wire.