



Systems 9 - 747-SL-20-048 - Fig. 20. Wing leading edge connector with lateral pressure due to missing backshell buildup and missing filler rods. This connector did have corrosion on the contacts.