



Systems 9 - 747-SL-20-048 - Fig. 21. Missing connector backshell buildup. Due to the harsh environment and high maintenance, the wing leading edge power drive units often exhibit installation deficiencies.