



Systems 9 - 747-SL-20-048 - Fig. 23. Damage to Teflon sleeving due to lacing tape internal to the sleeving. Boeing does not recommend the use of lacing tape inside sleeving or conduits.