



Systems 9 - 747-SL-20-048 - Fig. 25. Landing gear wire damaged by the debris thrown up by the tires. Here the damage was readily apparent.