



Systems 9 - 747-SL-20-048 - Fig. 28. When prior wire repairs are found, steps may need to be taken to ensure the damage is not repeated.