



Systems 9 - 747-SL-20-048 - Fig. 3. Sprung open raceway clamp. This creates additional stress on wire and adjacent clamps. In this instance no wire damage was observed.