



Systems 9 - 747-SL-20-048 - Fig. 31. The wire bundle crossover points in the wing leading edge can become damaged if they are not tied securely. (See reference document section 20-10-11))