



Power Feeder Cable
Chafing at
Clamping Points
7/27/80

Systems 9 - 747-SL-20-048 - Fig. 35. Power feeders chafing at clamping points.