



Systems 9 - 747-SL-20-048 - Fig. 36. Power feeders chafing at clamping points.