



Systems 9 - 747-SL-20-048 - Fig. 37. Bus Tie Breaker overheated due to incorrect lug build-up.