



W 1580 18°
FROM RIS
BOTH CLAMPS AND
STANDOFF BROKEN

Systems 9 - 747-SL-20-048 - Fig. 6. Failed bundle clamps and standoff. Again, wire and adjacent clamps experience additional stresses.