



Systems 9 - 747-SL-20-048 - Fig. 7. Bent clamp bracket causing excess bundle length further down the bundle.