



Systems 9 - 747-SL-20-048 - Fig. 9(a). In locations where wire bundles route through structure, caterpillar grommets or other protective material should be replaced when they fail.