



Systems 9 - 747-SL-30-048 - Fig. 32. Power feeders in good condition. Splices should be inspected for signs of over-heating.