


ATTACHMENT 3


Mode 2 – Excessive Terrain Closure Rate Plots

DCA02MA054
FedEx Flight 1478
GPWS Mode 2A - Excessive Terrain Closure Rate (Not In Landing Configuration)



PLOT 3-1

DCA02MA054
FedEx 1478 Flight
GPWS Mode 2B - Excessive Terrain Clearance Rate (Landing Configuration)



PLOT 3-2