



Systems 9 - Aging Aircraft Wire Testing - Photo 15.
Cracked after Gentle Handling.