



Systems 9 - Aging Aircraft Wire Testing - Photo 21.
Cracking following 148 hours at 200 degree C and Bend
Test.