



Systems 9 - Aging Aircraft Wire Testing - Photo 22.  
Cracking following 24 hours at 220 degrees C and Bend Test.