



Systems 9 - Electrical Short Circuit/Arcing of Aged Aircraft Wiring - Figure 39. Test 16 A: Damage sample after metal shaving abraders 90 degrees (right angle) test. Note that the broken wire was due to flexing and not the action of the shaving.