



Systems 9 - Exhibit No. 9A - Addendum 1 - (Fuel Probes) Photo 12. Fragment 80 Compensator internal HI-Z splice with blackened features at the bottom. Localized melting visible at bottom of left photo.