



Systems 9 - Exhibit No. 9A - Addendum 1 - (Fuel Probes) Photo 13. Fragment 80 Compensator interior. Bottom of HI-Z splice showing blackened plastic and deformation.