



Systems 9 - Exhibit No. 9B - Photo 1. Figure 1c. As received condition of the SPR circuit breaker. The upper arrow highlights the corroded terminal hardware. The lower arrow highlights the missing actuator stem and mounting bushing.