



Systems 9 - Exhibit No. 9B - Photo 1. Figure 1d. Wire sample submitted for analysis. The insulation exhibited blacked areas (black arrows) and mechanical damage (white arrows).