



Systems 9 - Exhibit No. 9B - Photo 12. Figure 12g. Hi-Z shield pigtail lead wire from N93110, sample #29. Damage occurred at edge of nylon strain relief clamp.