



Systems 9 - Exhibit No. 9B - Photo 13. Figure 13g-1. Elemental X-ray microanalysis of damaged Hi-Z shield pigtail lead wire from N93119, sample #29. X-ray microanalysis performed on boxed area (figure 12). Presence of copper & silver on PTFE insulation