



Systems 9 - Exhibit No. 9B - Photo 13. Figure 13g-2. Elemental X-ray microanalysis of damaged Hi-Z shield pigtail lead wire from N93119. Note presence of copper and silver on PTFE insulation at sites 1 and 2.