



Systems 9 - Exhibit No. 9B - Photo 16. Figure 16a. Scavenge pump switch plunger guide exhibiting surface cracks from the mold runner (arrow).