



Systems 9 - Exhibit No. 9B - Photo 18. Figure 18a. Evidence of internal salt water-like deposits on the scavenger pump switch case near the contact.